




XCR-A11, A51, B11, B51.




XCR-A12, A52, B12, B52.




XCR-A15, A55.



XCR-F17, F57; XCR-E18, E58.



Fixation supplémentaire par 2 pattes adaptables. / Fixing by 2 adjustable feet.  
Zusatzbefestigung, umsetzbar.



(1) 1 trou taraudé pour PE CM12.

(2) Longueur tige : 200 mm.

(3) Longueur tige + galet : 160 mm.

(4) Longueur tige :

XCR-E = 200 mm; XCR-F = 300 mm.

Ø 1 trou oblong 6x8.

Tapped hole for CM12 cable gland.

Lever length: 200 mm.

Lever + roller length: 160 mm.

Lever length:

XCR-E = 200 mm; XCR-F = 300 mm.

1 elongated hole 6x8 mm.

Gewindebohrung PE CM12 (PG 13,5).

Hebellaenge: 200 mm.

Laenge Hebel + Rolle: 160 mm.

Hebel-laenge:

XCR-E = 200 mm; XCR-F = 300 mm.






Langlochbohrung 6x8 mm.

XCR

Manufacturer :




**TMSS France**

Tour Eqho, 2 avenue Gambetta  
92400 Courbevoie - France



Our products should be installed, operated, serviced, and maintained only by qualified personnel. Neither TMSS France nor any of its subsidiaries or other affiliated companies shall be responsible or liable for any consequences arising out of the use of this material.

Telemecanique™ Sensors is a trademark of Schneider Electric Industries SAS used under license by TMSS France. Any other brands or trademarks referred to in this document are property of TMSS France or, as the case may be, of its subsidiaries or other affiliated companies. All other brands are trademarks of their respective owners.






XCR-A, B, C, D.  
A = 30°  
B = 55°  
C = 100 mm/daN.  
\* P = 40° - manœuvre positive d'ouverture  
- positive opening operation  
- Oeffner zwangstrennend.

XCR-J, K, L, P.  
A = 30°  
B = 90°  
C = 100 mm/daN.  
\* P = 65° - manœuvre positive d'ouverture  
- positive opening operation  
- Oeffner zwangstrennend.

XCR-E, F.  
D = 55°  
E = 90°  
C = 125 mm/daN.  
\* P = 65° - manœuvre positive d'ouverture  
- positive opening operation  
- Oeffner zwangstrennend.


~ (ac) 50-60 Hz




--- (dc)  
5 x 10^6 man.

24 V 48 V 120 V  
10 W 7 W 4 W


XCR-A1.




XCR-B1.




XCR-C1.




XCR-D1.




XCR-J1.




XCR-K1.




XCR-L1.




XCR-P1.






XCR-F17



XCR-E18




~ (ac) 50-60 Hz




--- (dc)  
5 x 10^6 man.

24 V 48 V 120 V  
7 W 9 W 13 W


XCR-A5.




XCR-B5.



XCR-C5.




XCR-D5.




XCR-J5.




XCR-K5.



XCR-L5.



XCR-P5.



XCR-F57



XCR-E58

