

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2323173-0
Report Reference E534034-20230725
Date 25-Jul-2023

Issued to: TMSS France, DBA Telemecanique Sensors
35 Rue Joseph Monier
Rueil Malmaison 92500
France

**This is to certify that
representative samples of**

NISD7 - Emergency Stop Devices Certified for Canada
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: CSA C22.2 No. 60947-1:22, 3rd Ed., Issue Date: 2022-5-31, IEC 60947-5-5, Edition 1, AMD 2, Issue Date 1997-11-26, Revision Date 2016-02-29

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Deborah Jennings-Conner
Deborah Jennings-Conner, VP Regulatory Services

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2323173-0
Report Reference E534034-20230725
Date 25-Jul-2023

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
XY2-CH, followed by 1, followed by 3 or 4, followed by 1, 2, 3, 4, 5, or 9, followed by 5, 7, or 9, followed by 0, may be followed by H7 or H29, may be followed by TK.	Emergency stop pushbuttons

Deborah Jennings-Conner

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

